

# Cranfield Helicopters Limited

## Helicopter Charter Operator & Training Organisation

---

### Component Overhaul



#### Helicopter Component Overhaul

Cranfield Helicopters are pleased to announce that they are now one of the small number of specialists that can now complete Helicopter Component Overhaul, Repair and Maintenance.

Gaining initial approval on Bell 206B & 206L Series please find attached the list of our capabilities.

With a combined experience of over 50 years in helicopter maintenance you can rest assured your component will be in safe hands.

With a turnaround time that can be tailored to our clients needs, a competitive pricing structure and a service of the highest quality now is the time to start looking at your overhaul needs.



#### 206 A/B/III Prices

Main Rotor Head Inspection	£990.00
Main Rotor Head Overhaul	£3,120.00
Main Rotor Flap Restraint	£510.00
Transmission Inspection	£1,350.00 / £1,500.00
Transmission Overhaul	£5,700.00
Mast Inspection	£690.00
Mast Overhaul	£1,200.00
Tail Rotor Gearbox Inspection	£900.00
Tail Rotor Gearbox Overhaul	£1,860.00
Tail Rotor Hub Overhaul	£990.00
Freewheel Inspection	£690.00
Freewheel Overhaul	£1,410.00
Swashplate Overhaul	£2,100.00

**Overhaul prices are basic overhaul costs, extra work (due to defects, corrosion etc.) and replacement parts are additional. The above prices are exclusive of VAT.**

To discuss your component overhaul, repair or maintenance requirements please call us on 01234 758112 or alternatively email us: [mail@cranfield-helicopters.com](mailto:mail@cranfield-helicopters.com)

